Sheet Molded Compound (SMC) Panel Bonding

This is intended to provide general guidelines for sheet molded compound (SMC) and carbon fiber adhesive bonding of full panel replacement in regards to collision repair procedures.

Sectioning, partial panel of full panels, is not supported by General Motors unless specifically documented in a Service Bulletin or Manual.

Important:

- Prepare the surfaces to be bonded according to adhesive manufacturer's recommendations. Many adhesive manufacturers have different preparation methods. Do not intermix adhesive manufacturers systems. Mixing materials from different manufacturers can produce unsatisfactory results.
- DO NOT top coat any adhesive bonding mating surface. Use primer only on bonding surfaces. Refer to adhesive manufacturer's recommendations for priming applications.

Adhesives currently meeting the performance requirements include General Motors materials and products manufactured by Ashland and Lord Fusor. At this time, ONLY the adhesive products listed below meet this guideline:

GM Goodwrench®	GMSPO of Canada	Structural Adhesives	Lord Fusor Structural Adhesive	Product Type
89020330	8902332	7770B	127 EZ	Medium Set
N/A	N/A	7779B	N/A	Fast Set
Canadian applications may use U.S. part numbers. Reter to your GM Dealer Parts Department for the correct part number applications.				

Document ID# 1655994 2006 Chevrolet Corvette

Sheet Molded Compound (SMC) Panel Bonding

This is intended to provide general guidelines for sheet molded compound (SMC) and carbon fiber adhesive bonding of full panel replacement in regards to collision repair procedures.

Sectioning, partial panel of full panels, is not supported by General Motors unless specifically documented in a Service Bulletin or Manual. Important:

- Prepare the surfaces to be bonded according to adhesive manufacturer's recommendations. Many adhesive manufacturers have different preparation methods. Do not intermix adhesive manufacturers systems. Mixing materials from different manufacturers can produce unsatisfactory results.
- DO NOT top coat any adhesive bonding mating surface. Use primer only on bonding surfaces. Refer to adhesive manufacturer's recommendations for priming applications.

Adhesives currently meeting the performance requirements include General Motors materials and products manufactured by Ashland and Lord Fusor. At this time, ONLY the adhesive products listed below meet this guideline:

GM Goodwrench®	GMSPO of Canada	Ashland Pliogrip Structural Adhesives Crest Industries, Inc 1-800-822-4100	Lord Fusor Structural Adhesive	Product Type
89020330	89020330 8902332 7770B 127 EZ Medium Set			
N/A N/A 7779B N/A Fast Set				
Canadian applications may use U.S. part numbers. Refer to your GM Dealer Parts Department for the correct part number applications.				

Document ID# 1655994 2008 Chevrolet Corvette

Sheet Molded Compound (SMC) Panel Bonding

This is intended to provide general guidelines for sheet molded compound (SMC) adhesive bonding of full panel replacement in regards to collision repair procedures:

Sectioning, partial panel of full panels, is not supported by General Motors unless specifically documented in a Service Bulletin or Manual:

Important: Prepare the surfaces to be bonded according to adhesive manufacturer's recommendations. Many adhesive manufacturers have different preparation methods. Do not intermix adhesive manufacturers systems. Mixing materials from different manufacturers can produce unsatisfactory results.

Important: DO NOT top coat any adhesive bonding mating surface. Use primer only on bonding surfaces. Refer to adhesive manufacturer's recommendations for priming applications.

Adhesives currently meeting the performance requirements include General Motors materials and products manufactured by Ashland and Lord Fusor. At this time, ONLY the adhesive products listed below meet this guideline:

GM Goodwrench®	GMSPO of Canada	Ashland Pliogrip Structural Adhesives Crest Industries, Inc 1-800-822-4100	Lord Fusor Structural Adhesive	Product Type
89020330	8902332	7770B	127 EZ	Medium Set
N/A N/A 7779B		N/A	Fast Set	
Canadian applications may use U.S. part numbers. Refer to your GM Dealer Parts Department for the correct part number applications.			ent for the	

Document ID# 1318299 2004 Cadillac XLR

Sheet Molded Compound (SMC) Panel Bonding

This is intended to provide general guidelines for sheet molded compound (SMC) and carbon fiber adhesive bonding of full panel replacement in regards to collision repair procedures.

Sectioning, partial panel of full panels, is not supported by General Motors unless specifically documented in a Service Bulletin or Manual. Important:

- Prepare the surfaces to be bonded according to adhesive manufacturer's recommendations. Many adhesive manufacturers have different preparation methods. Do not intermix adhesive manufacturers systems. Mixing materials from different manufacturers can produce unsatisfactory results.
- DO NOT top coat any adhesive bonding mating surface. Use primer only on bonding surfaces. Refer to adhesive manufacturer's recommendations for priming applications.

Adhesives currently meeting the performance requirements include General Motors materials and products manufactured by Ashland and Lord Fusor. At this time, ONLY the adhesive products listed below meet this guideline:

GM Goodwrench®	GMSPO of Canada	Ashland Pliogrip Structural Adhesives Crest Industries, Inc 1-800-822-4100	Lord Fusor Structural Adhesive	Product Type
89020330	89020330 8902332 7770B 127 EZ Medium Set			
N/A N/A 7779B N/A Fast Set				
Canadian applications may use U.S. part numbers. Refer to your GM Dealer Parts Department for the correct part number applications.				

Document ID# 1655994 2008 Cadillac XLR

Sheet Molded Compound (SMC) Panel Bonding

This is intended to provide general guidelines for sheet molded compound (SMC) and carbon fiber adhesive bonding of full panel replacement in regards to collision repair procedures.

Sectioning, partial panel of full panels, is not supported by General Motors unless specifically documented in a Service Bulletin or Manual.

Important:

- Prepare the surfaces to be bonded according to adhesive manufacturer's recommendations. Many adhesive manufacturers have different preparation methods. Do not intermix adhesive manufacturers systems. Mixing materials from different manufacturers can produce unsatisfactory results.
- DO NOT top coat any adhesive bonding mating surface. Use primer only on bonding surfaces. Refer to adhesive manufacturer's recommendations for priming applications.

Adhesives currently meeting the performance requirements include General Motors materials and products manufactured by Ashland and Lord Fusor. At this time, ONLY the adhesive products listed below meet this guideline:

Sheet Molded Compound (SMC) Panel Bonding

GM Goodwrench®	GMSPO of Canada	Ashland Pliogrip Structural Adhesives Crest Industries, Inc 1–800–822–4100	Lord Fusor Structural Adhesive	Product Type
89020330	89020332	7770B	127 EZ	Medium Set
N/A	N/A	7779B	N/A	Fast Set

Canadian applications may use U.S. part numbers. Refer to your GM Dealer Parts Department for the correct part number applications.

www.genuinegmparts.com

2000-2018 Chevrolet Corvette Collision Repair Manual

Metal Panel Bonding

This information is intended to provide general guidelines for adhesive bonding of steel panels. Panel bonding of steel is only recommended when the panel is originally bonded to the vehicle.

The adhesives listed in this document are known to meet the General Motors specifications and requirements for bonding of steel body panels.

Bonding procedures in general are applicable only at factory joints.

The use of adhesive to section steel panels is not recommended by General Motors.

Rivets, or other mechanical fasteners, may be used in combination with adhesive bonding of steel panels. The specified rivets, or fasteners, should be used with adhesive, when replacing the original panel.

Two types of adhesives are listed here. Impact Resistant Adhesive is used in joints in frame rail assemblies and strut tower assemblies and other body structure joints that have critical strength requirements. The factory applied Impact Resistant Adhesive is purple in color when cured. The Impact Resistant adhesives available for servicing these joints are considerably stronger once cured than panel bonding adhesives. The other bonding adhesives are non-impact resistant, offer a lower strength rating and can be used in all other joints that are not originally made with Impact Resistant Adhesive.

Note: Always follow the adhesive manufacturer's instructions for application, handling, and curing for the specific product.

Adhesives currently meeting the performance requirements include the adhesive products listed below meet these guidelines:

Steel Panel Bonding Impact Resistant

Manufacturer and Part Number	Description
Pliogrip 5770P	Pliogrip 5770P Structural Impact Durable Adhesive Available from Ashland 800-PLIOGRIP www.ashland.com/products/pliogrip-structural-adhesives
Fusor 2098	Fusor 2098 Impact Resistant Adhesive Available from Lord Fusor 800-234-3876 www.fusor.com
3M 07333	. 3M Impact Resistant Structural Adhesive Available from 3M شwww.3MCollision.com

Steel Panel Bonding

Manufacturer and Part Number	Description
GM P/N 12378566 (US)	Fast Set Panel Bonding Adhesive
GM P/N 88901674 (Canada)	
Lord Fusor P/N 110B/111B	
GM P/N 12378567 (US)	Medium Set Panel Bonding Adhesive
GM P/N 88901675 (Canada)	a .
Lord Fusor P/N 108B/109B	5
3M P/N 8116	Panel Bonding Adhesive
Ashland Plio Grip Panel 60 ©2015 General Motors. All rights reserved.	Panel Bonding Adhesive

www.genuinegmparts.com

2003-2018 Cadillac CTS Collision Repair Manual



Ashland Specialty Chemical

Division of Ashland Inc. P.O. Box 2219, Columbus, OH 43216 5200 Blazer Parkway, Dublin, OH 43017

PLIOGRIP[®] OEM ADHESIVE APPLICATIONS Automotive

PLIOGRIP[®] is the preferred adhesive for the Automotive manufacturers listed below and has been used in applications, including but not limited to...

Fender	Bumper
Hood	Lift Gate
Removable Hardtop	Grill
Deck Lid	Tail Gate
Spoiler	Roof
Window Clip	Roof Hatch
Valve-Cover Assembly	Quarter Panels

GENERAL MOTORS COMPANY – US Brands

PROGRAM	MODEL YEAR(S)
Pontiac Fiero	1984-1987
GM 200 Vans (GM Lumina, Pontiac	1988-1993
Transam, Olds Silhouette)	
Chevrolet Camaro CFIV	1994-2002
Pontiac Firebird CFIV	1994-2002
Chevrolet Corvette C1 – C4	1984-2004
Military (H1) Hummer	1983-2004
(Original: AMGeneral)	
H2 Hummer SUV	2002-2004
Pick-Up/Utility Trucks	
GMT 530 Med. Duty Truck	1993-2003
Buick Rendezvous Van	2002-2004
Buick Ranier	2004
GMT 802 C/K Chevrolet Avalanche	2003-2004
Truck	
Cadillac Escalade SUV	2003-2004
Cadillac XLR Roadster	2004

GENERAL MOTORS COMPANY – Opel

PROGRAM	MODEL YEAR(S)
Frontera	
Vectra GTS	



Ashland Specialty Chemical

Division of Ashland Inc. P.O. Box 2219, Columbus, OH 43216 5200 Blazer Parkway, Dublin, OH 43017

PLIOGRIP[®] OEM ADHESIVE APPLICATIONS Automotive

FORD MOTOR COMPANY - US BRANDS

PROGRAM	MODEL YEAR(S)
Mustang	2000-2004
Ranger Truck/Explorer SUV)	1995-2001
Excursion SUV	2000-2004
F-150 Truck	2000-2003
Windstar Van	1996-1998
Bronco Truck	1978-1992
Thunderbird	2001-2004
Bronco II Truck	1984-1994
Lincoln Continental	1996-2000
Aerostar Van	1986-1994

FORD MOTOR - Premium Automotive Group, Volvo Car

PROGRAM	MODEL YEAR(S)
V70	2000-2004
XC90	2004
Street Ka	2004

FORD MOTOR- Premium Automotive Group, Aston Martin

PROGRAM	MODEL YEAR(S)
V12 Vanquish	2002-2004

Daimler-Chrysler – Chrysler US Brands

PROGRAM	MODEL YEAR(S)
Dodge Viper	1995-2004
Jeep Wrangler	1982-2004
Jeep Liberty	2003-2004
Jeep Cherokee	1984-1998
Dodge Stratus	2003-2004
Dodge Neon	2003-2004
Prowler	2000-2001
PT Cruiser	2000-2004
Dodge DR Ram	2004



Ashland Specialty Chemical

Division of Ashland Inc. P.O. Box 2219, Columbus, OH 43216 5200 Blazer Parkway, Dublin, OH 43017

PLIOGRIP[®] OEM ADHESIVE APPLICATIONS Automotive

Daimler-Chrysler – Mercedes Benz

PROGRAM	MODEL YEAR(S)
SLR230	2000-2004

Daimler-Chrysler - MCC Group

PROGRAM	MODEL YEAR(S)
Smart Roadster	2005 Prototype

BMW

PROGRAM	MODEL YEAR(S)
Z3	1997-2003
Z4	2004
M3 CSL	2002-2004
Z8	2003-2004
3 Series Touring	2002
5 Series Touring	2004
X3 SUV	
X5 SUV	2003-2004

VOLKSWAGEN --Audi Group

PROGRAM	MODEL YEAR(S)
A4	2002-2004
A2	2004

VOLKSWAGEN

PROGRAM	MODEL YEAR(S)
Lupo GTI	2001-2004
Polo GTI	2001-2004
Tuareg SUV	2004

PORSCHE

PROGRAM	MODEL YEAR(S)
Cayenne SUV	2003-2004



Division of Ashland Inc. P.O. Box 2219, Columbus, OH 43216 5200 Blazer Parkway, Dublin, OH 43017

911 GT2 Carrera 4S	2004
Carrera 4S	2004
PLIOGRIP[®] OEM ADHESIVE APPLICATIONS	

Automotive

FERRARI

PROGRAM	MODEL YEAR(S)
F355	2000
F360 Modena	2002
F360 Evo	2004

ALFA ROMEO

PROGRAM	MODEL YEAR(S)
146	
156	
GTV Spider	1999-2004

MASERATI

PROGRAM	MODEL YEAR(S)
GT3200	

RENAULT

PROGRAM	MODEL YEAR(S)
Clio V6	

PEUGEOT

PROGRAM	MODEL YEAR(S)
807	
306	

CITREON

PROGRAM	MODEL YEAR(S)
C8	

FIAT

PROGRAM	MODEL YEAR(S)
Ulyssee	



Ashland Specialty Chemical

Division of Ashland Inc. P.O. Box 2219, Columbus, OH 43216 5200 Blazer Parkway, Dublin, OH 43017

Multipla

PLIOGRIP[®] OEM ADHESIVE APPLICATIONS Automotive

LANCIA		
PROGRAM	MODEL YEAR(S)	
Phedra		
MGF		
PROGRAM	MODEL YEAR(S)	
Spider	2002-2004	



Ashland Specialty Chemical

Division of Ashland Inc. P.O. Box 2219, Columbus, OH 43216 5200 Blazer Parkway, Dublin, OH 43017

PLIOGRIP[®] OEM ADHESIVE APPLICATIONS HEAVY TRUCK

PLIOGRIP[®] is also the preferred adhesive for the Heavy Truck manufacturers listed below and has been used in applications, including but not limited to...

Structural Assembly of Cab	Front Grill
Hood	Roof
Storage Doors	Fenders
Door Panel	High Roof

PACCAR – KENWORTH

PROGRAM	MODEL YEAR(S)
T2000	1998-2004
T600/T800	1994-2004
Т603	1996-2004
GENERAL	1994-2004

PACCAR – PETERBILT

PROGRAM	MODEL YEAR(S)
Model 387	2000-2004
Model P2100	2001-2004
Model 357	1993-2004

PACCAR- DAF

PROGRAM	MODEL YEAR(S)
XF95	2002-2004

PACCAR-ERF

PROGRAM	MODEL YEAR(S)
Various	2002-2004



Ashland Specialty Chemical

Division of Ashland Inc. P.O. Box 2219, Columbus, OH 43216 5200 Blazer Parkway, Dublin, OH 43017

PLIOGRIP[®] OEM ADHESIVE APPLICATIONS HEAVY TRUCK

Daimler-Chrysler: Commercial Vehicles, FREIGHTLINER Corp

PROGRAM	MODEL YEAR(S)
Century P2	1998-2004
Columbia	2001-2004
Business, M	2002-2004
Coronado	2002-2004
Classic/Classic XL	2002-2004
FLD	1990-2004

FREIGHTLINER - STERLING (formerly Ford Motor Heavy Truck)

PROGRAM	MODEL YEAR(S)
HN-80	1994-2004
PHN-177	1998-2004
PHN-180	2000-2004

NAVISTAR / International

PROGRAM	MODEL YEAR(S)
8100	
8200	
9200/9400	
Low Pro	
ProSleeper	
3000 IC bus	
Proline	
4000 series	

VOLVO TRUCK

PROGRAM	MODEL YEAR(S)
VN L-4 & L-5 (US)	1997-2004
Model 2287 (US)	2002-2004
WG	1992-1999
Prevost Bus (Canada)	
GENERAL (US)	
FH (Europe)	



Ashland Specialty Chemical

Division of Ashland Inc. P.O. Box 2219, Columbus, OH 43216 5200 Blazer Parkway, Dublin, OH 43017

PLIOGRIP[®] OEM ADHESIVE APPLICATIONS HEAVY TRUCK

VOLVO TRUCK--MACK Group

PROGRAM	MODEL YEAR(S)
Ultraliner	1986-1988
W, MD, CL	1988-1998
СН	1997-2004
Vision	2004

SCANIA

PROGRAM	MODEL YEAR(S)
Various	1990's+

FIAT --IVECO Truck

PROGRAM	MODEL YEAR(S)
Eurostar	
Stralis	2003

Case New Holland

PROGRAM	MODEL YEAR(S)
Tractor JXU	2004

GENERAL MOTORS VEHICLES MANUFACTURED WITH IMPACT RESISTANT STRUCTURAL ADHESIVE (IRSA)

<u>YEAR (S)</u>	VEHICLE
2010-CURRENT	CHEVROLET VOLT
2008-CURRENT	CHEVROLET CAMARO
2011-CURRENT	CHEVROLET MALIBU/BUICK REGAL
2014-CURRENT	CHEVROLET IMPALA/BUICK LACROSSE
2011-CURRENT	ALL CADILLAC PASSENGER CARS
2011-CURRENT	FULL SIZE TRUCKS/SUV'S
2015-CURRENT	CHEVROLET COLORADO/GMC CANYON
2014-CURRENT	CORVETTE C7
2010-CURRENT	CHEVROLET EQUINOX/GMC TERRAIN

PLEASE NOTE THAT ANY GM VEHICLE, 2015 AND NEWER, HAS BEEN MANUFACTURED WITH IMPACT RESISTANT STRUCTURAL ADHESIVE. ANY OEM ADHESIVE ON GM VEHICLES THAT IS PURPLE OR ORANGE (ORANGE IS NOT COMMON) IN COLOR <u>MUST</u> BE REPAIRED WITH PLIOGRIP[™] 5770P (OR GM APPROVED EQUIVALENT) TO ACHIEVE "PRE-ACCIDENT CONDITION".

VISIT: <u>WWW.GENUINEGMPARTS.COM</u> FOR CRASH REPAIR INFORMATION AND ADHESIVE RECOMMENDATIONS. PLIORGIP[™] 5770P IS LISTED AS AN APPROVED ADHESIVE FOR STRUCTURAL BONDING PROCEDURES.


#17-NA-258: Excessive Wind Noise from Front Side Door Glass Area - (Jul 31, 2019)

Subject: Excessive Wind Noise from Front Side Door Glass Area



Brondi	Madal	Mode	Model Year: VIN:		VIN:		
Brand:	Model:	from	to	from	to	- Engine:	Transmission:
Chevrolet GMC	Silverado 1500 Sierra 1500	2014	2014				
Chevrolet GMC	Silverado Sierra	2015	2018				
Chevrolet	Silverado LD Silverado 2500/3500	2010	2010			All	All
GMC	Sierra Limited Sierra 2500/3500	2019	2019				

Involved Region or Country	North America and N.A. Export Regions
Condition	Some customers may comment on hearing excessive wind noise coming from the front side door glass area.
Cause	The cause of the condition may be any of the following three primary factors:



9. Reinstall the front door trim panel, garnish molding, outside rearview mirror and belt reveal molding. Refer to *Front Side Door Window Belt Reveal Molding Replacement* in SI.

Parts Information

Description	Part Number	Qty	Contact Information
Kent® Ure-Foam Expandible Foam Sound Deadener*	P 10630		Contact Kent Automotive at 1- 888-937-5368 or <u>Kent Automotive</u>
3M™ Flexible Foam*	08463	1	<u>3M</u>
Crest ® Flexi Foam (Two Part Flexible Urethane)*	CF-F		Crest Auto
SEM Dual-Mix™ Flexible Urethane Foam*	39357		SEM products
Kent ® High Tech Clear Seam Sealer*	P 10200		Contact Kent Automotive at 1- 888-937-5368 or Kent Automotive
3M™ Heavy Drip-Chek™ Sealer*	08531	1	<u>3M</u>
Crest Clear Drip Seal*	TJ-C		Crest Auto
Wurth Euroseal Gel*	08920104		Wurth USA

© 2019 General Motors. All rights reserved.



Program Bulletin



CUSTOMER SATISFACTION PROGRAM

SUBJECT: Enhancements for Side Impact Pole Performance

MODELS: 2011-2012 Chevrolet Volt

CONDITION

The 2011 and 2012 model year Chevrolet Volt vehicles passed all Motor Vehicle Safety Standards. A vehicle inspection following a side pole test, however, indicated that the vehicle experienced structural intrusion of approximately 50 mm into the battery, which may rupture the coolant line causing coolant leakage. If a vehicle with a leaking coolant system was left on its side or in an inverted position for an extended period of time, the coolant could flow onto the battery electronic controls on top of the battery pack. If the battery pack had not been depowered, after several days (at least 6 and likely much longer), a short circuit may occur and result in a vehicle fire.

CORRECTION

Dealers are to add a reinforcement bracket to further protect the battery pack in a severe side collision, replace the battery coolant system reservoir with a new reservoir that includes a sensor to monitor the coolant level, and add a tamper-resistant bracket to the top of the battery coolant reservoir to help prevent potential coolant overfills.

VEHICLES INVOLVED

Involved are all 2011 model year and certain 2012 model year Chevrolet Volt vehicles.

Important: Dealers are to confirm vehicle eligibility prior to beginning repairs by using the Required Field Actions section in the Global Warranty Management system. Not all vehicles may be involved.

For dealers with involved vehicles, a listing with involved vehicles containing the complete vehicle identification number, customer name, and address information has been prepared and will be provided to US and Canadian dealers through the GM GlobalConnect Recall Reports, or sent directly to export dealers. Dealers will not have a report available if they have no involved vehicles currently assigned.

The listing may contain customer names and addresses obtained from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than follow-up necessary to complete this program is a violation of law in several states/provinces/countries. Accordingly, you are urged to limit the use of this report to the follow-up necessary to complete this program.

PART INFORMATION

Parts required to complete this program are to be obtained from two different sources.

Parts listed in the table below are to be obtained from General Motors Customer Care and Aftersales (GMCC&A). Please refer to your "involved vehicles listing" before ordering parts. Normal orders should be placed on a DRO = Daily Replenishment Order. In an emergency situation, parts should be ordered on a CSO = Customer Special Order.

Part numbers 22920448, 22922225, and 19260759 are not eligible for RIM.


Part Number	Description	Quantity/Vehicle
22920448	Reinforcement Kit, F/FIr Tun	1
22922225	Battery Kit, Drv Mot (bottle/sensor kit)	1
19260759	Connector, Wrg Harn	1
12378390 - US 10953456 - CN	Coolant, Engine	2

The part listed in the table below is to be obtained from **Crest Industries**, **Inc.** by calling 1-800-822-4100 (U.S.) or J-2 Products at 1-888-880-0025 or 416-665-1404 (Canada), 8:00 am - 4:30 pm ET.

Part Number	Description	Quantity/Vehicle
7770B220	Ashland Pliogrip	<mark>1</mark>

SERVICE PROCEDURE

Perform a visual inspection of the drive motor battery cooling system reservoir fluid level BEFORE completing the service repairs in this bulletin.



- If the coolant level of the drive motor cooling system reservoir is below the seam of the reservoir (1), perform leak inspection diagnostics BEFORE proceeding to the service repair in this bulletin. Refer to SI for the appropriate leak inspection diagnostic information. Submit a warranty claim for leak inspection diagnostics and service repairs. After completing the inspection and repairs, proceed to the service repairs in this bulletin.
- If the drive motor cooling system reservoir is **NOT below the seam of the reservoir (1)**, proceed to the service repairs in this bulletin.

Note: The service repairs in this bulletin must be performed at a GM dealership that is authorized to perform Volt repair work. Only Volt certified technicians are to perform the repairs in this bulletin.

Battery Tunnel Reinforcement Installation

Note: The following tools are required to complete the battery tunnel reinforcement procedure:

- A compact quality drill.
- Drill bits that will drill through high strength steel. The drill bits are provided in kit P/N22920448.
- A pneumatically powered pop rivet gun that accepts 6.35 mm (¼ in), 4.76 mm (3/16 in), 3.96 mm (5/32 in) and 3.17 mm (1/8 in) rivets.
- Dual Cartridge Applicator for Pliogrip two-part polyurethane
- Small disposable brush for spreading the Pliogrip two-part polyurethane
- Butyl, 3M P/N 08578, 3M P/N 08612, or equivalent.
- RTV, P/N 88864346, (or equivalent)

Danger: Always perform the High Voltage Disabling procedure prior to servicing any High Voltage component or connection. Personal Protection Equipment (PPE) and proper procedures must be followed. The High Voltage Disabling procedure includes the following steps:


- Identify how to disable high voltage.
- Identify how to test for the presence of high voltage.
- Identify condition under which high voltage is always present and personal protection equipment (PPE) and proper procedures must be followed.

Before working on any high voltage system, be sure to wear the following Personal Protection Equipment:

- Safety glasses with appropriate side shields when within 15 meters (50 feet) of the vehicle, either indoors or outdoors.
- Certified and up-to-date Class "0" Insulation gloves rated at 1000V with leather protectors.
- Visually and functionally inspect the gloves before use.
- Wear the Insulation gloves with leather protectors at all times when working with the high voltage battery assembly, whether the system is energized or not.

Failure to follow the procedures may result in serious injury or death.

1. Disconnect and remove the high-voltage battery from the vehicle. Refer to *Drive Motor Battery Replacement and Shipping* in SI.



2756827


Caution: Do not pry on or contact the battery RESS cover while removing the aluminum crush limiters with screwdriver.

2. Remove the 4th and 5th aluminum crush limiters (indicated with red arrows in illustration) from the driver's and passenger's side of the battery RESS cover.






- 2.1 Place the tip of a small flat-blade screwdriver against the bottom of each aluminum crush limiter. Access the bottom of the crush limiter through the hole on the bottom side of the battery RESS cover.
- 2.2 Gently tap the end of the screwdriver with a small hammer. You may have to work around the bottom of the aluminum crush limiter, tapping it in a few locations to completely free the aluminum crush limiter from the cover.



Note: Butyl should **only** be applied in the chamfer (red face) of the crush limiter. Refer to illustration. Butyl should not be present in the metal-to-metal joint between RESS cover, reinforcement plate and longitudinal rails.

3. Apply a butyl-based sealer such as 3M Ribbon Sealer 08612 or 3M Strip-Caulk 08578 (or equivalent) on the chamfer of the new aluminum crush limiters, P/N 22917161.



Note: The aluminum crush limiters are chamfered and must be installed with chamfer side down.

4. Press the four new aluminum crush limiters (1), P/N 22917161, into the battery RESS cover where the aluminum crush limiters were removed.



2756843

- 5. Install the new aluminum crush limiters by tapping lightly and evenly with small hammer.
- 6. Remove the excess butyl on the RESS cover.





 Attach the reinforcement assembly (1) to the car body using the four shorter M10 bolts from the kit. Tighten bolts to 25 Nm (19 lb-ft). Make sure the reinforcement assembly is centered from side to side within the tunnel of the vehicle body.



8. Locate the front and rear plates to the car body and hold in position using two hand clamps or "C" clamps. Make sure the front and rear plates are centered from side to side on the tunnel reinforcement of the vehicle body.



- 2756888
- 9. Center punch all of the holes in the plates and reinforcement assembly before drilling the 3mm (1/8 in) pilot holes.

Caution: To increase the useful life of the drill bit, drill the holes into the vehicle body at a low speed. The appropriate drill speed will allow the drill bit to cut into the metal efficiently. The drill bit will remove metal chips or metal shavings from the high strength steel quickly if the appropriate drill speed is used. Ensure the drill used at a low speed for steps 10-14.

- 10. Drill 3mm (1/8 in) pilot holes into the vehicle body through the 20 existing holes in the front and rear plates. The three lower holes per plate will also go through the reinforcement assembly.
- 11. Drill 6.75mm (17/64 in) holes through the 20 pilot holes.
- 12. Remove the clamps and the front and rear plates. Set aside the plates.

Caution: To avoid vehicle damage, place a drill stop on drill bits to ensure drill does NOT enter the vehicle beyond 19 mm ($\frac{3}{4}$ in) in depth.

Drill 3mm (1/8 in) pilot holes into the vehicle body through the 28 existing holes in the reinforcement assembly. Do not allow the drill bit to enter the vehicle body beyond 19 mm (³/₄ in) in depth for the six upper holes on each side.





Caution: To avoid vehicle damage, place a drill stop on drill bits to ensure drill does NOT enter the vehicle beyond 19 mm ($\frac{3}{4}$ in) in depth.

- Drill 6.75mm (17/64 in) holes through the 28 pilot holes from step 13. Use a drill stop or otherwise do not allow the drill bit to enter the car body beyond 19 mm (3/4 in) in depth for the six upper holes on each side.
- 15. Remove the four M10 bolts and the reinforcement assembly from the vehicle body. Set aside the reinforcement assembly and the bolts.
- 16. Deburr all of the drilled holes in the front and rear plates, the reinforcement assembly, and the vehicle body. Remove any metal shavings from the surfaces of the front and rear plates, the reinforcement assembly, and the vehicle body.
- 17. Clean all mating surfaces of the front and rear plates, the reinforcement assembly, and the vehicle body using isopropyl (rubbing) alcohol and a clean, lint-free cloth. Allow the alcohol to dry.





Caution: Ensure the Pliogrip two-part polyurethane mix is uniform in color BEFORE applying it to the parts. Discard the first 25 mm (1 in) of the mix that is not uniform. The color of the polyurethane varies. The illustrations in this bulletin show the polyurethane mix in black or green. The Pliogrip two-part polyurethane has a 30-minute open time. The application of the Pliogrip two-part polyurethane and the assembly of the reinforcement assembly must be completed in 30 minutes.

18. Apply approximately 5mm (3/16 in) beads of Pliogrip two-part polyurethane, P/N 7770B220, in the patterns shown onto the reinforcement assembly and the front and rear plates. Use a new mixing and dispensing tip, and ensure that both components of the polyurethane are dispensing and mixing from the dispensing tip prior to applying the polyurethane to the parts.




19. Coat drill holes and exposed metal with Pliogrip, P/N 7770B220, two-part polyurethane using a brush as shown in illustration.



2756872

Re-attach the reinforcement assembly to the vehicle body using the four shorter M10 bolts (1). Tighten bolts to 25 Nm (19 lb-ft). Make sure the reinforcement assembly is centered from side to side within the tunnel of the vehicle body. Ensure that the 6.75mm (17/64 in) holes drilled into the reinforcement assembly are aligned.





Caution: To ensure the pop rivets are installed correctly, use two hand clamps or "C" clamps to hold the plates into position. Make sure the rear plate is pressed against the vehicle body in each location as each rivet is being installed.

- 21. Re-locate the rear plate and install the 7 pop rivets (2), P/N 11561547, through the upper 6.75mm (17/64 in) holes. Make sure the rear plate is pressed against the vehicle body in each location as each pop rivet is being installed.
- 22. Re-locate the front plate and install 7 pop rivets (2), P/N 11561547, through the upper 6.75mm (17/64 in) holes. Make sure the front plate is pressed against the vehicle body in each location as each pop rivet is being installed.
- 23. Install the remaining 28 pop rivets (2), P/N 11561547, through the 6.75mm (17/64 in) holes of the reinforcement assembly. Make sure the reinforcement assembly is pressed against the vehicle body in each location as each pop rivet is being installed.

Note: The six longer rivets (3), P/N 11569698 are to be located in bottom of the front and rear plates.

- 24. Install the six pop rivets (3), P/N 11569698, through the lower 6.75mm (17/64 in) holes that were also drilled through the reinforcement assembly. Ensure the plate is pressed against the reinforcement assembly in each location as each pop rivet is being installed.
- 25. Grind flush any pop rivet mandrels that did not break off flush with the rivet head.
- 26. Wipe off any excess polyurethane that squeezed out around the reinforcement assembly or around the front and rear plates.




27. Apply RTV, P/N 88864346 (or equivalent), on and around each of the six upper rivet heads along each side of the reinforcement assembly. The other rivet head locations do not require sealer.

Caution: Remove and **discard** the four short M10 bolts from the reinforcement assembly. Discard the M10 and M8 bolts removed from the high-voltage battery. The battery tunnel reinforcement kit, PN 22920448, contains new M8 and M10 bolts. Use the new bolts to install the high-voltage battery to avoid vehicle damage.

- 28. Remove the four M10 bolts from the reinforcement assembly. Discard the M10 bolts.
- 29. Re-install and re-connect the high voltage battery using the 18 new M10 bolts, P/N 11588740, and four new M8 bolts, P/N 11588724, from the kit. Refer to Drive Motor Battery Replacement and Shipping in SI.
- 30. Lower the vehicle. Refer to Lifting and Jacking the Vehicle in SI.


HV Battery/Inverter Surge Tank Replacement and Coolant Level Sensor Jumper Harness Installation

1. Remove battery reservoir cap from coolant surge tank.




2393887

2. Remove front compartment sight shield.



3. Remove windshield washer filler tube (1) by pulling up on it.



4. Remove radiator upper mounts (2).



Caution: Do NOT use a prybar or similar tool to move the radiator module rearward, or damage to the radiator module can result.

Note: If accessing the surge tank-to-fan shroud fasteners is difficult, remove the radiator upper crossbar to gain access to the fasteners.

5. Push condenser/radiator/fan/module rearward and remove the two coolant surge tank fasteners (1).




- 6. Empty the power inverter module cooling system reservoir using the Vac-N-Fill system with 152 mm (6 in) hose extension.
- 7. Clamp shut power inverter module cooling system reservoir hoses.




- 8. Disconnect all hoses for both reservoirs of the coolant surge tank. Remove the battery coolant pump inlet hose, battery coolant cooler outlet hose, battery radiator outlet hose and generator control module coolant tank hose.
- 9. Remove the coolant surge tank.
 - 9.1 Remove engine/intake cover.




- 9.2 Remove A/C refrigerant pressure sensor connector (1).
- 9.3 Wiggle coolant surge tank out of engine compartment.
- 10. Install coolant level sensor jumper harness.




- 10.1 Unplug refrigerant temperature sensor (3).
- 10.2 Pull out the wire harness.
- 10.3 Unseat Christmas tree retainer (1).
- 10.4 Disconnect compressor connector (2).
- 10.5 Remove harness clip from hose (4).



10.6 Cut off the wires at the back of the refrigerant temperature sensor (1) connector and strip 13 mm (1/2 in) of insulation from the two wire ends (2).



10.7 Locate the coolant level sensor jumper from service kit 19260759 and strip 13 mm (1/2 in) of insulation from the two wire ends.




- 2757181
- 10.8 Crimp connect white and black wires on the new kit harness to the white/blue and black/violet wires respectively using the splice clip provided in the service kit. Refer to the instructions provided in the kit for proper procedure and tools.



2757184

10.9 Apply heat to the splice clip/heat shrink to seal it to the wire insulation. Proper tools must be used to protect the wire insulation from excess heat.




10.10 Install the new corrugated tube (1) that is provided in the service kit over the harness splice. The corrugated tube should overlap existing harness corrugated tube on both sides.

- 10.11 Completely wrap new corrugated tube with black electrical tape.
- 10.12 Reinstall the wire harness.
- 10.13 Install harness clip on hose in specified area.
- 10.14 Replug the compressor connector.
- 10.15 Reseat the Christmas tree retainer (replace if damaged).



10.16 Install new harness clip (from the kit) on the A/C line above existing harness clip.



10.17 Put a dime-sized dab of RTV, P/N 88864346, (or equivalent) over exposed refrigerant temperature sensor (1) to cover exposed terminals.



- 11. Install the new coolant surge tank.
- 12. Connect coolant level sensor to new coolant surge tank.
- 13. Reconnect all coolant surge tank hoses.
- 14. Push radiator toward the engine and secure the driver's side (left) mount coolant surge tank fastener (1) by installing and tightening the one bolt.
- 15. Reconnect A/C refrigerant pressure sensor connector.
- 16. Remove manual clamp from power inverter module cooling system reservoir hoses.

Note: Vac-N-Fill equipment must be used along with proper coolant. The Power Electronics / Charging and Battery Cooling systems require a 50/50 mix of DEX-COOL[®] and de-ionized water. This mixture is available in a pre-mix with bitterant, P/N 12378390 USA, P/N10953456, Canada. The pre-mixed coolant is no longer available without the bitterant chemical. Refer to P/I #PIP4910.

17. Vac-N-Fill the power inverter module cooling system reservoir.



17.1 Use the VAC-N-FILL equipment without the 152 mm (6 in) hose extension.

- 17.2 Pull vacuum (at least 15 in Hg) for five (5) minutes.
- 17.3 Fill while under vacuum.
- 17.4 Remove reservoir overflow port cap.
- 17.5 Install overflow tubing and reservoir cap.

Note: Vac-N-Fill equipment must be used along with proper coolant. The Power Electronics / Charging and Battery Cooling systems require a 50/50 mix of DEX-COOL[®] and de-ionized water. This mixture is available in a pre-mix with bitterant, P/N 12378390 USA, P/N10953456, Canada. The pre-mixed coolant is no longer available without the bitterant chemical. Refer to P/I #PIP4910.

18. Vac-N-Fill the battery cooling system reservoir.



- 18.1 Use the VAC-N-FILL equipment without the 152 mm (6 in) hose extension.
- 18.2 Pull vacuum (at least 15 in Hg) for 5 minutes.
- 18.3 Fill while under vacuum.
- 18.4 Again pull vacuum (at least 15 in Hg) for 5 minutes.
- 18.5 Fill to top of reservoir.
- 18.6 Re-enable the high voltage battery. Refer to *Drive Motor Battery Replacement and Shipping* in SI.

Note: Do not attempt to order the calibration number from GM Customer Care and Aftersales. The calibration numbers required for this service procedure are programmed into control modules via a Multiple Diagnostic Interface (MDI) and TIS2WEB with the calibration update. When using the MDI for reprogramming, ensure that it is updated with the latest software version. Use **TIS2WEB on or after 02/10/12** to obtain the calibration. If you cannot access the calibration, call the Techline Customer Support Center and it will be provided.

For step-by-step programming instructions, please refer to SI and the Techline Information System (TIS) terminal.

- 19. Verify that there is a battery charge of 12 to 15 volts. The battery must be able to maintain a charge during programming. Only use an approved Midtronics® PSC 550 Battery Maintainer (SPS Programming Support Tool EL-49642) or equivalent to maintain proper battery voltage during programming.
- 20. Reprogram the modules listed in step 20.3. Refer to SI and Service Programming System (SPS) documentation for programming instructions.
 - 20.1 Connect the MDI to the vehicle. Connect the MDI to the programming terminal with a cable.
 - 20.2 Select J2534 MDI and Reprogram ECU from the Select Diagnostic Tool and Programming Process screen.

Note: Ensure that the hood is open and turn the vehicle ON to Service Mode. The Service Mode can be attained by pressing and holding the power button for 5 to 8 seconds WITHOUT depressing the brake pedal. Make sure that the ICE does not come on during this process.

20.3 Determine module year of vehicle.


Note: For 2011 vehicles, ensure that the most recent version of field action bulletin 11137 has been completed BEFORE performing the programming event in this bulletin.

- For 2011 model year vehicles, select SEQ Programming Sequence Battery Energy Control Module (K15) and Hybrid Powertrain Control Module 2 (K114B) from the Supported Controllers screen.
- For 2012 model year vehicles, select Hybrid Powertrain Control Module 2 (K114B) from the Supported Controllers screen.


20.4 Follow the on-screen instructions.

Caution: The Coolant level will drop below reservoir during this process. If it does, do not break vacuum, but use the Vac-N-Fill equipment to fill the reservoir. Next, re-establish the 15 in Hg vacuum for the remainder of the fill procedure. You may have to fill the reservoir several times during this procedure to prevent a low coolant condition, which will induce air into the system. If at the end of the procedure, the fluid level is below the reservoir, fill the reservoir and repeat the MDI/GDS Hybrid/EV Battery Pack Coolant Pump Bleed Procedure.


- 21. Run MDI/GDS2 "Hybrid/EV Battery Pack Coolant Pump Bleed Procedure" test <u>while</u> <u>maintaining the 15 in Hg vacuum throughout</u> the process. This procedure will take about an hour to complete.
 - 21.1 Launch GDS2 and select Diagnostics.
 - 21.2 Ensure information is accurate on the Vehicle Selection screen and then press ENTER.
 - 21.3 Select Module Diagnostics and then press ENTER.
 - 21.4 Select Hybrid Powertrain Control Module 2 and then press ENTER.
 - 21.5 Select Control Function and then press ENTER.
 - 21.6 Select Hybrid/EV Battery Pack Coolant Pump Bleed Procedure and then press ENTER.
 - 21.7 Adjust (remove or add) coolant level to max fill line.
 - 21.8 Install overflow tubing and reservoir cap.
- 22. Clear diagnostic codes (DTCs) if necessary.
- 23. Disconnect the low voltage battery charger.
- 24. Turn vehicle off.



25. Reinstall radiator mounts (2). Tighten bolts to 22 Nm (16 lb-ft).



- 26. Reinstall windshield washer filler tube (1).
- 27. Reinstall engine/intake cover.
- 28. Road test the vehicle in Mountain Mode with the vehicle in Low Gear for approximately 5 miles (8 km). When performing the 5 mile (8 km) mile drive cycle, drive vehicle in slalom (side to side motion) to purge any remaining air.




29. Re-check coolant level. Ensure the coolant level is to the top of the tank seam (1).



2757164

30. Install locking bracket (1) on vehicle right side reservoir securing the bracket and the reservoir with the bolt provided in the kit. Tighten bolt from front side of tie bar.



2393887

- 31. Reinstall front compartment sight shield.
- 32. Wash the vehicle.
- 33. Fill the fuel tank.
- 34. Check tire pressure. Add air to tires if required.
- 35. Fully charge the high-voltage battery before returning the vehicle to the customer.

COURTESY TRANSPORTATION - For US and Canada

The General Motors Courtesy Transportation program is intended to minimize customer inconvenience when a vehicle requires a repair that is covered by the New Vehicle Limited Warranties. The availability of courtesy transportation to customers whose vehicles are within the warranty coverage period and involved in a product program is very important in maintaining customer satisfaction. Dealers are to ensure that these customers understand that shuttle service or some other form of courtesy transportation is available and will be provided at no charge. Dealers should refer to the General Motors Service Policies and Procedures Manual for Courtesy Transportation guidelines.

WARRANTY TRANSACTION INFORMATION

Submit a transaction using the table below.

Labor Code	Description	Labor Time	Net Item
V2533	Install Battery Reinforcement Brkt, Coolant Sensor, Coolant Tank	7.0	*
T5848	Battery Charge, Tire Inflate, Vehicle Wash, & if applicable, Fill Tank	0.7	**

- * Submit the cost of the adhesive required to perform the repair, not to exceed \$29.70 USD, \$32.60 CAD, plus shipping.
- ** Submit the cost to fill the fuel tank in the Misc field.

CUSTOMER NOTIFICATION – For US and Canada

General Motors will notify customers of this program on their vehicle (see copy of customer letter included with this bulletin).

CUSTOMER NOTIFICATION – For Export

Letters will be sent to known owners of record located within areas covered by the US National Traffic and Motor Vehicle Safety Act. For owners outside these areas, dealers should notify customers using the attached sample letter.

DEALER PROGRAM RESPONSIBILITY

All unsold new vehicles in dealers' possession and subject to this program <u>must</u> be held and inspected/repaired per the service procedure of this program bulletin <u>before</u> customers take possession of these vehicles.

Dealers are to service all vehicles subject to this program at no charge to customers, regardless of mileage, age of vehicle, or ownership, from this time forward.

Customers who have recently purchased vehicles sold from your vehicle inventory, and for which there is no customer information indicated on the involved vehicle listing, are to be contacted by the dealer. Arrangements are to be made to make the required correction according to the instructions contained in this bulletin. A copy of the customer letter is provided in this bulletin for your use in contacting customers. Program follow-up cards should not be used for this purpose, since the customer may not as yet have received the notification letter.

In summary, whenever a vehicle subject to this program enters your vehicle inventory, or is in your facility for service in the future, you must take the steps necessary to be sure the program correction has been made before selling or releasing the vehicle.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the tools, equipment, safety instructions, and know-how to do a job properly and safely. If a condition is described, <u>DO NOT</u> assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your dealer for information on whether your vehicle may benefit from the information.



We Support Voluntary Technician Certification (Letter for customers with 2011 MY vehicles - US Only)

February 2012

Dear Volt Customer:

GM is now ready to implement the Volt vehicle enhancements that you were informed of in January.

We will be making enhancements to the battery coolant system and vehicle structure. Specifically, your Chevrolet dealer will add a reinforcement bracket to further protect the battery pack in a severe side collision, replace the battery coolant system reservoir with a new reservoir that includes a sensor to monitor the coolant level, reprogram the high voltage battery diagnostic module to allow for low coolant sensing, and add a tamper-resistant bracket to the top of the battery coolant reservoir to help prevent potential coolant overfills. This service will be performed at no charge.

In the fall of 2011, a software update was made available to you through Customer Satisfaction Program 11137. This updated software is required to perform the service above. If your vehicle does not already have this updated software, it will be installed for you at the same time, again, at no charge. Your vehicle's estimated electric vehicle range displayed in the instrument cluster will be reset. This <u>will not</u> affect your actual electric vehicle range. Within a short period of time, the displayed electric vehicle range will adjust to reflect an estimate more consistent with your normal driving range.

We recommend that you contact your dealer at your convenience to schedule an appointment on or after March 19. Upon request, your dealer will also provide you with courtesy transportation while your vehicle is at the dealership.

If you have any questions that your dealer is unable to answer, please contact your Volt advisor. The contact information is 877-4-VOLT-INFO (877-486-5846) or Voltda101@gmexpert.com.

We want you to know that we will do our best, throughout your ownership experience, to ensure that your Chevrolet Volt provides you many miles of enjoyable driving.

ine Sile Das

Alicia Boler-Davis U.S. Vice President Customer Experience

11342-1

(Letter for customers with 2012 MY vehicles - US & Canada Only)

February 2012

Dear Volt Customer:

GM is now ready to implement the Volt vehicle enhancements that you were informed of in January.

We will be making enhancements to the battery coolant system and vehicle structure. Specifically, your Chevrolet dealer will add a reinforcement bracket to further protect the battery pack in a severe side collision, replace the battery coolant system reservoir with a new reservoir that includes a sensor to monitor the coolant level, reprogram the high voltage battery diagnostic module to allow for low coolant sensing, and add a tamper-resistant bracket to the top of the battery coolant reservoir to help prevent potential coolant overfills. This service will be performed at no charge.

Your vehicle's estimated electric vehicle range displayed in the instrument cluster will be reset. This <u>will not</u> affect your actual electric vehicle range. Within a short period of time, the displayed electric vehicle range will adjust to reflect an estimate more consistent with your normal driving range.

We recommend that you contact your dealer at your convenience to schedule an appointment on or after March 19. Upon request, your dealer will also provide you with courtesy transportation while your vehicle is at the dealership.

If you have any questions that your dealer is unable to answer, please contact your Volt advisor. The contact information is 877-4-VOLT-INFO (877-486-5846) or Voltda101@gmexpert.com.

We want you to know that we will do our best, throughout your ownership experience, to ensure that your Chevrolet Volt provides you many miles of enjoyable driving.

11342-2

we Sil Das

Alicia Boler-Davis U.S. Vice President Customer Experience



Document ID: 3980423

#PI1314: Creak/Pop Type Noise from Right Front of Vehicle During Low Speed Maneuvers - (Sep 17, 2014)
Subject: Creak/Pop Type Noise from Right Front of Vehicle During Low Speed Maneuvers
2014-2015 Chevrolet Equinox
Models: 2014-2015 GMC Terrain
All Built Prior to August 5, 2014

Condition/Concern

Some customers may comment on a front body creak/pop type noise when turning the steering wheel when the vehicle is stationary or during slow speed maneuvers. This noise is located in the front passenger foot well area.

This condition may be caused by an insufficiently tightened cradle mount bolt or two out of position spot welds within the front right frame rail.


Recommendation/Instructions

Use the following steps to diagnose and correct the condition:


- 1. Road test the vehicle to verify the condition.
- 2. Raise the vehicle. Refer to Lifting and Jacking the Vehicle in SI.
- 3. Check the front suspension crossmember to body mounting bolts. Tighten the bolts 155 \u2224 Y (114 \u2224 lb \u2224 ft).
- 4. Road test the vehicle and determine if the condition is corrected.
 - If the condition is corrected, the repair is complete.
 - If the noise is still present, continue to the next step.
- 5. Remove the right front seat. It is not necessary to completely remove the seat from the vehicle. Fold the right rear seat down and place the seat assembly on the cargo floor. Refer to Driver or Passenger Seat Removal and Installation in SI.
- 6. Remove the right side console trim plate. Refer to Front Floor Console Trim Plate Replacement in SI.
- 7. Remove the right front hinge pillar trim. Refer to Body Hinge Pillar Trim Panel Replacement in SI.
- 8. Fold back the right front carpet but do not remove the carpet from the vehicle.
- 9. Remove the HVAC blower motor. Refer to Blower Motor Replacement in SI.




10. Remove the body plug. Save the plug as it will be reused.




11. Using a gasket scraper, remove the sound deadener material from the repair area as shown.




12. Measure up from the body hole $90 \square mm$ (3.5 \square in) (1). Create a cross car line (2).




13. Measure up from that line an additional 50□mm (2.0□in) (1). Create a second cross car line (2).




14. From the center mark, measure 45 □mm (1.75 □in) in both directions (1). Create two lines connecting the cross car lines.




15. Using a cut off wheel, cut along both cross car lines and the inboard connecting line.



16. Bend the tab back revealing the two spot welds as shown.




- 17. Create two drill locations $6 \square mm$ (0.25 \square in) down from the edge of the metal.
 - Locate the inboard mark slightly to the left of the spot weld.
 - Locate the outboard mark above the spot weld.
- 18. Center punch the drill locations.




- 19. Drill two 0.25 □ in holes.
- Prepare a small quantity of *Crest Industries CB-M1 "Black Majik" 10 minute adhesive. Follow the manufacturers instructions for prepping cartridge and dispensing adhesive.




21. Coat the two #11519023 rivets as shown.




22. Install the two rivets. Using a small brush, cover the rivets with the material squeeze out.




23. Prepare a quantity of Crest Industries CE-JB "Jet Black" 1.5 minute adhesive. Follow the manufacturers instructions for prepping cartridge and dispensing adhesive. Coat the edges of the metal tab and opening.



24. Bend the tab back into position and add additiona CE-JB "Jet Black" adhesive to the joint. Hold in position while the material cures.



- 25. Reinstall the body plug.
- 26. Prepare a quantity of Crest Industries CB-M1 "Black Majik" adhesive and apply to the complete area. Using a plastic spreader, coat the complete area.
- 27. Prepare 3 150 \square mm (6.0 \square in) long strips of fiberglass mesh tape.



28. Install the tape cross car in the vehicle overlapping the complete area. Use a small brush to saturate the tape with adhesive.



- 29. Apply an additional coat of Crest Industries CB-M1 "Black Majik" adhesive. Use a plastic spreader to smooth the repair area.
- 30. Reinstall the HVAC blower motor. Refer to Blower Motor Replacement in SI.
- 31. Reinstall the carpet, right side console trim plate, right hinge pillar trim and the seat. Refer to the appropriate SI procedures listed above.

*We believe these sources and their products to be reliable. There may be additional manufacturers of such material. General Motors does not endorse, indicate any

preference for or assume any responsibility for the products from these firms or for any such items which may be available from other sources

Parts Information

The adhesive material, fiberglass mesh tape and brushes can be ordered directly from Crest Industries Inc. at 1 (800) 822-4100. Canadian Dealers: Call J-2 Products (Crest Distributor) at 1-888-880-0025 or 416-665-1404, 8:00 am - 5:00 pm ET.

	Part Number	Description	Material Allow:	ance
	11519023	Rivet	2	
	*CB-M1	Crest "Black Majik" Adhesive Kit	1	
	*CE-JB	Crest "Jet Black" Adhesive Kit	1	
Warra	anty Information			

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
1480368*	Install Two Structural Rivets To Frame Rail	1.7 hrs

*This is a unique Labor Operation for Bulletin use only. It will not be published in the Labor Time Guide.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.

WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATIO N

© 2014 General Motors. All rights reserved.